



CBS Europe Srl

[www.cbs.it](http://www.cbs.it)

[cbs@cbs.it](mailto:cbs@cbs.it)

Tel. 071.7232409

Fax 071.7232408

## CROSS REFERENCE INDUCTOR



|                      |                 |                     |
|----------------------|-----------------|---------------------|
| 3L GLOBAL            | DELEVEN         | PULSE               |
| ABRACON              | DELTA           | RENCO               |
| ACT                  | DIGI-KEY        | SAMSUNG ELECTRONICS |
| ADVANCED CERAMICS    | ECM ELECTRONICS | SIEMENS             |
| AEM                  | EPCOS           | SMEC                |
| ALLIED COMPONENTS    | E-TRONIC        | SPRAGUE-GOODMAN     |
| AMIDON, INC.         | FASTRON         | STETCO              |
| API                  | FAIR RITE       | STETNER             |
| BI TECHNOLOGIES      | FERROXCUBE      | SUMIDA              |
| BOURNS               | FRONTIER        | TOKIN               |
| CAMBION              | GOWANDA         | TOKO                |
| CAL-CHIP ELECTRONICS | INDUCTOR SUPPLY | TAIYO YUDEN         |
| CERATECH             | J.W. MILLER     | TDK                 |
| CHILISIN             | KOA             | TSC ELECTRONICS     |
| COIL WINDING SP      | MAG LAYERS      | UNICOM KOREA        |
| COILCRAFT            | MIDCOM          | WEST CAP            |
| COOPER/COILTRONICS   | MURATA          | WILCO               |
| CT                   | NIC COMPONENTS  | ULTRACOIL           |
| DALE                 | PANASONIC       | XFMR INC            |



## 3L GLOBAL

| Viking     | 3L GLOBAL    | Viking   | 3L GLOBAL   |
|------------|--------------|----------|-------------|
| SCDB2D10   | BRI2D10      | PDH1608  | SMTDR0402HC |
| SCDB2D12   | BRI2D12      | PDH1813  | SMTDR0504HC |
| SCDB2D15   | BRI2D15      | PDH3316  | SMTDR0804HC |
| SCDB2D18   | BRI2D18      | PDH4920  | SMTDR1105HC |
| SCDS4D12   | SMTDRRI4D12  | PDH5022  | SMTDR1306HC |
| SCDS4D18   | SMTDRRI4D18  | PCDS63B  | SMTDRRI63B  |
| SCDS5D18   | SMTDRRI5D18  | PCDS74B  | SMTDRRI74B  |
| NL08(1008) | SMDMS2520    | PCDS105B | SMTDRRI105B |
| NL10(1210) | SMDMS3225    | PCDS125B | SMTDRRI125B |
| NL12(1812) | SMDMS4532    | PS1608   | SMTDRRI0402 |
| NL20(2220) | SMDMS5620    | PS3308   | SMTDRRI0804 |
| WL02(0402) | SMDCHGR0402S | PS5022   | SMTDRRI1206 |
| WL03(0603) | SMDCHGR0603S | PSDB5D28 | SMTDRH5D28R |
| WL05(0805) | SMDCHGR0805  | PSDB1003 | SMTDRH103R  |
| WL08(1008) | SMDCHGR1008  | PSDB1004 | SMTDRH104R  |
| CPS1008    | SMDFSR1008PS | PSDB1005 | SMTDRH105R  |
| PCD0301    | SMTDR31      | PCS62B   | SMTDRRI62B  |
| PCD0302    | SMTDR32      | PCS64B   | SMTDRRI64B  |
| PCD0403    | SMTDR43      | PCS73    | SMTDRRI73   |
| PCD0504    | SMTDR54      | PCS74    | SMTDRRI74   |
| PCD0703    | SMTDR73      | PCS124   | SMTDRRI124  |
| PCD0705    | SMTDR75      | PCS125   | SMTDRRI125  |
| PCD1004    | SMTDR104     | PCS127   | SMTDRRI127  |
| PCD1005    | SMTDR105     | PCDR0628 | SMTDRS0628  |
| VLH322515  | SMTSDR322515 | PCDR0728 | SMTDRS0728  |
| VLH322520  | SMTSDR322520 | PCDR0730 | SMTDRS0730  |
| VLH453226  | SMTSDR453226 | PCDR0732 | SMTDRS0732  |
| VLH575047  | SMTSDR575047 | PCDR0745 | SMTDRS0745  |
| PD1608     | SMTDR0402    | PCDR1045 | SMTDRS1045  |
| PD3308     | SMTDR0802    | PCDR1255 | SMTDRS1255  |
| PD3316     | SMTDR0804    | PCDR1265 | SMTDRS1265  |
| PD3340     | SMTDR0810    | PCDR1275 | SMTDRS1275  |
| PD5022     | SMTDR1206    |          |             |



## ABRACON

| Viking      | ABRACON     | Viking     | ABRACON    |
|-------------|-------------|------------|------------|
| CB100(1210) | ACB1210MA   | PS1608     | ASPI-0403S |
| CL01(0201)  | AIMC-0201   | PD1608     | ASPI-0603  |
| CL02 (0402) | AIMC-0402   | PS1608     | ASPI-0603C |
| CL03(0603)  | AIMC-0603   | PCS73      | ASPI-0703S |
| CL05(0805)  | AIMC-0805   | PCS74      | ASPI-0704S |
| ML02(0402)  | AIML-0402   | PSDB1004   | ASPI-104S  |
| ML03(0603)  | AIML-0603   | PSDB1004   | ASPI-105S  |
| ML05(0805)  | AIML-0805   | PCS125     | ASPI-1205S |
| ML06(1206)  | AIML-1206   | PCS127     | ASPI-1207S |
| WL02(0402)  | AISC-0402   | PCS127     | ASPI-1207S |
| WL03(0603)  | AISC-0603   | PS5022     | ASPI-1306S |
| WL05(0805)  | AISC-0805   | PCF4020    | ALPL4020   |
| WL08(1008)  | AISC-1008   | MPE0312    | ASPI-0312  |
| NL08(1008)  | AISC-1008F  | AL01(0201) | ATFC0201   |
| VLH322520C  | AISC-1210H  | AL02(0402) | ATFC0402   |
| VLH322520C  | AISC-1210RH | AL03(0603) | ATFC0603   |
| VLH453226   | AISC-1812H  | CB02(0402) | ACML-0402  |
| VLH453226   | AISC-1812RH | CB03(0603) | ACML-0603  |
| NL08(1008)  | AIMS-1008   | CB05(0805) | ACML-0805  |
| NL10(1210)  | AIMS-1210   | CB06(1206) | ACML-1206  |
| NL12(1812)  | AIMS-1812   |            |            |



## ACT

| Viking     | ACT           |
|------------|---------------|
| CB03(0603) | ACB-0603      |
| CB05(0805) | ACB-0805      |
| CB06(1206) | ACB-1206      |
| CB12(1812) | ACB-1812      |
| CB03(0805) | BCB-0805      |
| CB06(1206) | BCB-1206      |
| CB12(1812) | BCB-1812      |
| CB06(1206) | CBG1206-70-50 |
| NL10(1210) | CM1210B       |
| NL12(1812) | CM1812        |
| CB06(1206) | DCB-1206      |
| CB10(1210) | DCB-1210      |
| CB06(1206) | HCB-1206      |
| NL08(1008) | IC1008        |
| NL10(1210) | IC1210        |
| NL12(1812) | IC1812        |
| CB03(0603) | ICB-0603      |
| CB05(0805) | ICB-0805      |
| CB06(1206) | ICB-1206      |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## ADVANCED CERAMICS

| Viking     | ADVANCED CERAMICS |
|------------|-------------------|
| CL02(0402) | HI1005            |
| CL03(0603) | HI1608            |
| CL05(0805) | HI2012            |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## AEM

| Viking     | AEM      |
|------------|----------|
| CB02(0402) | MCB0402G |
| CB03(0603) | MCB0603G |
| CB05(0805) | MCB0805F |
| CB06(1206) | MCB1206F |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## ALLIED COMPONENTS

| Viking | ALLIED COMPONENTS |
|--------|-------------------|
| CB     | MLB05-102         |
| CB     | MLB10-100         |
| CB     | MLB20-102         |
| CB     | MLB40-800         |
| CB     | MLB50-700         |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## **AMIDON, INC.**

| <b>Viking</b> | <b>AMIDON, INC.</b> |
|---------------|---------------------|
| CB05(0805)    | MCB-201209-170      |





CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## API

| Viking | API    |
|--------|--------|
| PS1608 | SDS130 |
| PS3316 | SDS680 |
| PS5022 | SDS850 |
| PCS62B | SPD62  |
| PCS73  | SPD73  |
| PCS74  | SPD74  |
| PCS125 | SPD125 |
| PCS127 | SPD127 |



## BI TECHNOLOGIES

| Viking     | BI TECHNOLOGIES |
|------------|-----------------|
| NL1812     | BCL453232       |
| CB12(1812) | BMB-V-453215    |
| CL03(0603) | BMC0603HF       |
| CL05(0805) | BMC0805HF       |
| SCDS3D16   | HM66-10         |
| SCDS4D18   | HM66-20         |
| SCDS4D28   | HM66-30         |
| SCDS5D18   | HM66-40         |
| SCDS5D28   | HM66-50         |
| SCDS6D28   | HM66-60         |
| SCDS6D38   | HM66-70         |
| PSDB1004   | HM66-80         |
| PDH3316    | HM75-20         |
| PCS73      | HM78-30         |
| PCS74      | HM78-40         |
| PCS127     | HM78-45         |
| PCS125     | HM78-50         |
| PCS127     | HM78-60         |



## BOURNS

| Viking     | BOURNS        |
|------------|---------------|
| CL02(0402) | CI100505      |
| CL03(0603) | CI160808      |
| CL05(0805) | CI201210      |
| CL02(0402) | CM100505      |
| NL12(1812) | CM453232      |
| ML03(0603) | CS160808      |
| ML05(0805) | CS201212      |
| ML06(1206) | CS321613      |
| WL03(0603) | CW160808      |
| WL05(0805) | CW201212      |
| WL08(1008) | CW252016      |
| PCD0302    | SDR0302       |
| PCD0302    | SDR0302(LF)   |
| PCD0403    | SDR0403       |
| PCD0504    | SDR0604       |
| PCD0705    | SDR0805       |
| PD3316     | SDR1005       |
| PCD1005    | SDR1006(BRNS) |
| PD5022     | SDR1806       |
| PD5022     | SDR1806(L)    |
| PCS125     | SRR1206       |
| PCS125     | SRR1206(L)    |
| PCS127     | SRR1208       |
| PS5022     | SRR1806       |
| PS1608     | SRR6603       |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## CAMBION

| Viking     | CAMBION  |
|------------|----------|
| WL02(0402) | 555-0402 |
| WL03(0603) | 555-0603 |
| WL05(0805) | 555-0805 |
| WL08(1008) | 555-1008 |
| PCD0403    | 555-8060 |
| PCD0504    | 555-8062 |
| PCD0703    | 555-8064 |
| PCD0705    | 555-8066 |
| PCD1005    | 555-8068 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## CAL-CHIP ELECTRONICS

| Viking     | CAL-CHIP ELECTRONICS |
|------------|----------------------|
| CB05(0805) | FB201209T-102YS      |
| CB05(0805) | FB321611T-201Y-      |
| ML03(0603) | GLF1608              |
| ML05(0805) | GLF2125              |
| ML06(1206) | GLF3216              |
| NL08(1008) | NL2520(CAL)          |
| NL10(1210) | NL3225(CAL)          |
| NL12(1812) | NL4532(CAL)          |
| PD5022     | SSL1306              |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## CERATECH

| Viking     | CERATECH  |
|------------|-----------|
| CL05(0805) | CI-B2012  |
| ML05(0805) | FI-A2012  |
| ML06(1206) | FI-B3216  |
| CB         | HB-1H3216 |
| CB         | HB-1H4532 |
| CB         | HB-1M2012 |
| CB         | HB-1M3216 |
| CB         | HH-1H4532 |



## CHILISIN

| Viking              | CHILISIN   | Viking     | CHILISIN |
|---------------------|------------|------------|----------|
| CL02(0402)          | CLH1005    | ML03(0603) | CL1608   |
| CL03(0603)          | CLH1608    | ML05(0805) | CL2012   |
| CL05(0805)          | CLH2012    | ML06(1206) | CL321611 |
| WL03(0603)          | CS/LCN0603 | SCD0403    | PCD0403  |
| WL05(0805)          | CS/LCN0805 | SCD0504    | PCD0504  |
| WL08(1008)          | CS/LCN1008 | SCD0703    | PCD0703  |
| CB Standard         | SB         | SCD0705    | PCD0705  |
| CB (H) High current | PB         | SCD1004    | PCD1004  |
| NL252018            | NL252018T  | SCD1005    | PCD1005  |
| NL322522            | NL322522T  | SDS0402    | PS1608   |
| NL453232            | NL453232T  | SDS0804    | PS3316   |
| NL565250            | NL565250T  | SDS1306    | PS5022   |
| VLH322520           | SQV322520T | SLF0628    | PCDR0628 |
| VLH453226           | SQV453225T | SLF0728    | PCDR0730 |
| VLH321618(C)        | SQC321618  | SLF0730    | PCDR0730 |
| VLH322520(C)        | SQC322520  | SLF0732    | PCDR0732 |
| VLH453252(C)        | SQC453252  | SLF0745    | PCDR0745 |
| VLH575047(C)        | SQC575047  | SLF1255    | PCDR1255 |
| PD1608              | SSL0402    | SLF1265    | PCDR1265 |
| PD3308              | SSL0802    | SLF1275    | PCDR1275 |
| PD3316              | SSL0804    |            |          |
| PD3340              | SSL0810    |            |          |
| PD5022              | SSL1306    |            |          |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## COIL WINDING SP

| Viking   | COIL WINDING SP |
|----------|-----------------|
| PCDS1045 | SB-1004         |





## COILCRAFT

| Viking      | COILCRAFT     |
|-------------|---------------|
| CPS1008     | 100PS         |
| WL02(0402)  | 0402CS        |
| WL05(0805)  | 0508SC        |
| WL03(0603)  | 0603CS        |
| WL03(0603)H | 0603HC        |
| WL03(0603)  | 0603HS        |
| WL03(0603)  | 0608HS        |
| WL05(0805)  | 0805CS        |
| WL05(0805)H | 0805HQ        |
| WL05(0805)  | 0805HS        |
| WL05(0805)H | 0805HT        |
| WL08(1008)  | 1008CS        |
| WL08(1008)  | 1008HS        |
| WL08(1008)  | 1008SC        |
| WL06(1206)  | 1206CS        |
| WL06(1206)  | 1206CS(L)     |
| WL06(1206)  | 1206HS        |
| PD1608      | DO1608        |
| PD1608      | DO1608C       |
| PD3308      | DO3308P       |
| PD3316      | DO3316P       |
| PD3340      | DO3340P       |
| PD5022      | DO5022P       |
| PS1608      | DS1608C       |
| PS3316      | DS3316P       |
| PS5022      | DS5022P       |
| PDH3316     | DO3316H(ROHS) |
| PDH5022     | DO5010P-HC    |
| PDH1813     | DO1813HC      |
| PSDB1004    | MSS1038       |
| SCDS5D28    | MSS7341       |
| PCS127      | MS1278        |
| PCS125      | MSS126        |



## COOPER/COILTRONICS

| Viking     | COOPER/COILTRONICS |
|------------|--------------------|
| PSDB1004   | CD1                |
| PSDB1004   | CD1-R              |
| NL10(1210) | CTX32T             |
| NL10(1210) | CTX32T-R           |
| PCS125     | DR125              |
| PCS125     | DR125-R            |
| PCS127     | DR127              |
| PCS127     | DR127-R            |
| PCS73      | DR73               |
| PCS73      | DR73-R             |
| PCS74      | DR74               |
| PCS74      | DR74-R             |
| PCD0403    | LD1(CTX)           |
| PCD0705    | LD2(CTX)           |
| PCD0705    | LD2-R              |
| PDH1813    | UP1B               |
| PDH3316    | UP2                |
| PDH3316    | UP2B               |
| PDH3316    | UP2B-R             |
| PSDB1003   | DR1030             |
| PSDB1004   | DR1040             |
| PSDB1005   | DR1050             |

**CT**

| Viking                | CT               | Viking      | CT               |
|-----------------------|------------------|-------------|------------------|
| SCDS2D11              | CTCRH2D11        | PCD0302     | CTGS32           |
| SCDS2D11 High current | CTCRH2D11 HPH    | PCD0403     | CTGS43           |
| SCDS2D18              | CTCDRH2D11       | PCD0504     | CTGS54           |
| SCDS2D18 High Current | CTCDRH2D11 HPH   | PCD0703     | CTGS73           |
| SCDS3D16              | CTCDRH3D16       | PCD0705     | CTGS75           |
| SCDS4D18              | CTCDRH4D18       | PCD1004     | CTGS104          |
| SCDS4D28              | CTCDRH4D28       | PCD1005     | CTGS105          |
| SCDS5D18              | CTCDRH5D18       | MPI0610     | CTLPO1704        |
| SCDS5D28              | CTCDRH5D28       | MPI0915     | CTLPO25060B      |
| SCDS6D28              | CTCDRH6D28       | PCDS63B     | CTCDR63B         |
| SCDS6D38              | CTCDRH6D38       | PS5022      | CTDS5022         |
| PCS62B                | CTCDRH62BF       | PSDB1004    | CTCDRH104        |
| PCS64B                | CTCDRH64B        | PSDB1005    | CTCDRH105        |
| PCS73                 | CTCDRH73/73B/73C | CB          | CTCBF-Standard   |
| PCS74                 | CTCDRH74/74B/74C | CB (H)      | CTCBF-High speed |
| PCS124                | CTCDRH124        | CL02(0402)  | CTLH1005H        |
| PCS125                | CTCDRH125        | CL03(0603)  | CTLH1608H        |
| PCS127                | CTCDRH127        | CL02(0402)  | CTLL1005         |
| PS1608                | CTDS1608         | CL03(0603)  | CTLL1608         |
| PS3316                | CTDS3316         | ML03(0603)  | CTML0603         |
| PS5022                | CTDS5022         | ML05(0805)  | CTML0805         |
| PCDR0628              | CTSLF0628        | ML06(1206)  | CLML1206         |
| PCDR0732              | CTSLF0732        | AL01(0201)  | CTTTF0201F       |
| PCDR0745              | CTSLF0745        | AL02(0402)  | CTTF0402F        |
| PCDR1045              | CTSLF1045        | AL03(0603)  | CTTF0603F        |
| PCDR1275              | CTSLF1275        | WL02(0402)  | CT0402CSF        |
| PCDS74                | CTGSR74B         | WL03(0603)  | CT0603CSF        |
| PCDS105               | CTGSR105B        | WL03(0603)H | CT0603HC         |
| PCD0403               | CTCR43F          | WL05(0805)  | CT0805CSF        |
| PCD0703               | CTCR73F          | NL05(0805)  | CT0805FSF        |
| PD1608                | CTD01608         | WL08(1008)  | CT1008CSF        |
| PD1608                | CTD01608         | WL08(1008)H | CT1008HQF        |
| PD1813                | CTD01813HC       | WL06(1206)  | CT1206CSF        |
| PD3308                | CTD03308         | VLH321618   | CTLQ1206NF       |
| PD3316                | CTD03316         | VLH322515   | CTLQ1210N        |

|         |            |            |           |
|---------|------------|------------|-----------|
| PDH3316 | CTDO3316HC | VLH453226  | CTLQ1812N |
| PD3340  | CTDO3340   | NL08(1008) | CTMC1008  |
| PD5022  | CTDO5022   | NL10(1210) | CTMC1210  |
| PDH5022 | CTDO5022HC | NL20(2220) | CTMC2220  |
| DRGH654 | CTCH654F   | NL10(1210) | CTNLV32F  |
| DRGH664 | CTCH664F   | NL08(1008) | CT1008LSC |
| DRGH855 | CTCH855F   | DRGH875    | CTCH875F  |
| DRGH895 | CTCH895F   |            |           |



## DALE

| Viking  | DALE      |
|---------|-----------|
| PD1608  | IDC-2512  |
| PD3316  | IDC-5020  |
| PD5022  | IDC-7328  |
| PCD0403 | IDCP-1813 |
| PCD0504 | IDCP-2218 |
| PCD0705 | IDCP-3020 |
| PCD0703 | IDCP-3114 |
| PCD1005 | IDCP-3722 |
| PCD1004 | IDCP-3916 |
| PS1608  | IDCS-2512 |
| PS3316  | IDCS-5020 |
| PS5022  | IDCS-7328 |
| CB      | ILB-1206  |
| CB      | ILB1206RK |
| CB      | ILBB-0805 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## DELEVEN

| Viking     | DELEVEN |
|------------|---------|
| WL02(0402) | 0402R   |
| WL03(0603) | 0603R   |
| WL05(0805) | 0805R   |



## DELTA

| Viking   | DELTA    |
|----------|----------|
| WL03(H)  | 0603CC   |
| PD3316   | LCD104-A |
| PD3308   | LCD104-A |
| PD3308   | LCD104-B |
| PD3340   | LCD104-C |
| PD1608   | LCD44-A  |
| PSDB1004 | SHD115   |
| SCDS5D18 | SIL620   |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## DIGI-KEY

| Viking     | DIGI-KEY     |
|------------|--------------|
| WL08(1008) | M1(PM1008)   |
| PCD1005    | M1000(1-24)  |
| PCDS105B   | M1000(25-45) |
| NL12(1812) | M1100(01-49) |
| WL05(0805) | M1100(50-75) |
| PCD0403    | M3(PM43)     |
| PCD0403    | M4(PM54)     |





CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## ECM ELECTRONICS

| Viking     | ECM ELECTRONICS |
|------------|-----------------|
| NL08(1008) | ECM25T          |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## EPCOS

| Viking | EPCOS  |
|--------|--------|
| PD3316 | B82476 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## E-TRONIC

| Viking     | E-TRONIC |
|------------|----------|
| CB         | MCB1608S |
| CB         | MCB2012S |
| CL03(0603) | MCI1608  |
| CL05(0805) | MCI2012  |



## FASTRON

| Viking     | FASTRON  |
|------------|----------|
| WL02(0402) | 0402AS   |
| WL03(0603) | 0603AD   |
| WL03(0603) | 0603AS   |
| ML03(0603) | 0603MLF  |
| WL05(0805) | 0805A    |
| WL05(0805) | 0805AD   |
| WL05(0805) | 0805AS   |
| CL05(0805) | 0805MLA  |
| ML05(0805) | 0805MLF  |
| WL08(1008) | 1008AD   |
| WL08(1008) | 1008AS   |
| WL06(1206) | 1206AS   |
| ML06(1206) | 1206MLF  |
| PCD1004    | PDA104   |
| PCD1005    | PDA105   |
| PCD0403    | PDA43    |
| PCD0504    | PDA54    |
| PCD0703    | PDA73    |
| PCD0705    | PDA75    |
| PSDB1004   | PDRH104R |
| PCS124     | PDRH124  |
| PCS127     | PDRH127  |
| SCDS4D18   | PDRH4D18 |
| SCDS4D28   | PDRH4D28 |
| SCDS5S18   | PDRH5D18 |
| SCDS5D28   | PDRH5D28 |
| SCDS6D28   | PDRH6D28 |
| SCDS6D38   | PDRH6D38 |
| PCS73      | PDRH73   |
| PD1608     | PISG     |
| PD3308     | PISL     |
| PD3316     | PISM     |
| PD3340     | PISN     |
| PD5022     | PISR     |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## FAIR RITE

| Viking     | FAIR RITE    |
|------------|--------------|
| CL02(0402) | 220402-C     |
| ML03(0603) | 220603       |
| CL03(0603) | 220603-C     |
| ML05(0805) | 220805       |
| CL05(0805) | 220805-C     |
| ML06(1206) | 221206       |
| CB         | 2504021007Y0 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## FERROXCUBE

| Viking     | FERROXCUBE |
|------------|------------|
| CL02(0402) | MLH0402    |
| CL03(0603) | MLH0603    |
| CL05(0805) | MLH0805    |
| ML03(0603) | MLI0603    |
| ML05(0805) | MLI0805    |
| ML06(1206) | MLI1206    |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## FRONTIER

| Viking     | FRONTIER    |
|------------|-------------|
| NL08(1008) | 1008F(FRON) |
| NL12(1812) | 293A        |
| NL10(1210) | CF322522    |
| NL12(1812) | CF453232    |
| CB         | FB2012      |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## GOWANDA

| Viking     | GOWANDA |
|------------|---------|
| WL03(0603) | CC0603  |
| WL05(0805) | CC0805  |
| WL08(1008) | CC1008  |





## INDUCTOR SUPPLY

| Viking     | INDUCTOR SUPPLY |
|------------|-----------------|
| WL03(0603) | LC0603          |
| WL05(0805) | LC0805          |
| WL08(1008) | LC1008          |
| PCDS105    | LC105S          |
| NL12(1812) | LC1812          |
| PCD0403    | LC43            |
| PCS0504    | LC54            |
| PCD0705    | LC75            |
| PCD0705    | LC75S           |
| CL02(0402) | LCHF0402        |
| CL03(0603) | LCHF0603        |
| CL05(0805) | LCHF0805        |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## J.W.MILLER

|               |                    |
|---------------|--------------------|
| <b>Viking</b> | <b>J.W. MILLER</b> |
| PCD0504       | PM54               |



## KOA

| Viking      | KOA          |
|-------------|--------------|
| NL08(1008)  | KL25         |
| NL10(1210)  | KL32         |
| NL10(1210)  | KL32C        |
| NL10(1210)  | KL32L        |
| NL10(1210)  | KL32T        |
| AL01(0201)  | KL731H       |
| AL02(0402)  | KL731E       |
| AL03(0603)  | KL73J        |
| WL02(0402)  | KQ0402       |
| WL03(0603)  | KQ0603       |
| WL03(0603)  | KQ0603L      |
| WL03(0603)  | KQ0603T      |
| WL05(0805)  | KQ0805       |
| WL05(0805)  | KQ0805L      |
| WL05(0805)  | KQ0805T      |
| WL08(1008)  | KQ1008       |
| WL08(1008)  | KQ1008L      |
| WL08(1008)  | KQ1008T      |
| WL03(0603)H | KQC0603      |
| ML03(0603)  | MCI0603(KOA) |
| ML05(0805)  | MCI0805(KOA) |
| ML06(1206)  | MCI1206(KOA) |
| ML03(0603)  | MCL1J        |
| ML05(0805)  | MCL2A        |
| ML06(1206)  | MCL2B        |
| CL02(0402)  | MHL1J(L)     |
| CL03(0603)  | MHL2A(L)     |
| CL05(0805)  | MHL2A(T)     |
| PCD0504     | SDR0604L     |
| PCD0504     | SDR0604T     |
| PCD0705     | SDR0805(KOA) |
| PCD0705     | SDR0805L     |
| PCD0705     | SDR0805T     |
| PCD1005     | SDR1006(KOA) |
| PCD1005     | SDR1006L     |
| PCD1005     | SDR1006T     |



## MAG LAYER

| Viking     | MAG LAYERS  | Viking      | MAG LAYERS         |
|------------|-------------|-------------|--------------------|
| WL03(0805) | HFC-1608    | PS1608      | MSCDRB-0403        |
| WL05(0805) | HFC-2012C   | PS3316      | MSCDRB-0905        |
| WL08(1008) | HFC-2520C   | PS5022      | MSCDRB-1507        |
| CB03       | MLB1608     | PCS62B      | MSCDRI-63          |
| CB05       | MLB2012     | PCS64B      | MSCDRI-64          |
| CB06       | MLB321611   | PCS73       | MSCDRI-73          |
| PCD0302    | MSCD-32     | PCS74       | MSCDRI-74          |
| PCD0403    | MSCD-43     | PCS124      | MSCDRI-124         |
| PCD0502    | MSCD-52     | PCS125      | MSCDRI-125         |
| PCD0503    | MSCD-53     | PCS127      | MSCDRI-127         |
| PCD0504    | MSCD-54     | PCDS63B     | MSCDRI-63B         |
| PCD0703    | MSCD-73     | PCDS74B     | MSCDRI-74B         |
| PCD0705    | MSCD-75     | PCDS105B    | MSCDRI-105B        |
| PCD1004    | MSCD-104    | VLH322520   | MSCH-3225Q         |
| PCD1005    | MSCD-105    | VLH453226   | MSCH-4532Q         |
| PCD1006    | MSCD-106    | CL05 (0805) | HFI-201209 (0805)  |
| PD1608     | MSCDB-0603  | CL03 (0603) | HFI-160808 (0603)  |
| PD3308     | MSCDB-1303  | CL02 (0402) | HFI-100505 (0402)  |
| PD3316     | MSCDB-1305  | CL01 (0201) | HFI-060303 (0201)  |
| PD3340     | MSCDB-1311  | ML06 (1206) | GMLI-321611(1206)  |
| PD5022     | MSCDB-1807  | ML05 (0805) | GMLI-201212 (0805) |
| PDH1813    | MSCDB-0905H | ML05 (0805) | GMLI-201209 (0805) |
| PDH3316    | MSCDB-1305H | ML03 (0603) | GMLI-160808 (0603) |
| PDH4920    | MSCDB-1807H | ML02 (0402) | GMLI-100505 (0402) |
| PDH5022    | MSCDB-2207H |             |                    |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## MIDCOM

| Viking | MIDCOM   |
|--------|----------|
| PD5022 | DHC-7328 |



## MURATA

| Viking       | MURATA |
|--------------|--------|
| PCD0403      | 2300   |
| PCDS63B      | 2300S  |
| PCD0504      | 2400   |
| PCDS74B      | 2400S  |
| PCD1005      | 2600   |
| CB02 (0402)  | BLM15A |
| CB03H (0603) | BLM18P |
| CB05H (0805) | BLM21P |
| CB04H (1204) | BLM31P |
| CB08H(1808)  | BLM41P |
| CB02 (0402)  | BLM15B |
| CB03 (0603)  | BLM18B |
| CB05 (0805)  | BLM21B |
| CB04 (1204)  | BLM31B |
| CB08 (1808)  | BLM41B |
| VLH322520C   | LQH32C |
| VLH453226C   | LQH43C |
| VLH575047C   | LQH55D |
| AL01 (0201)  | LQP03T |
| AL02 (0402)  | LQP15M |
| AL03 (0603)  | LQP11A |
| WL02 (0402)  | LQW15A |
| WL03 (0603)  | LQW18A |
| WL05 (0805)  | LQW2BH |
| WL06 (1206)  | LQW31H |



## NIC COMPONENTS

| Viking     | NIC COMPONENTS | Viking   | NIC COMPONENTS |
|------------|----------------|----------|----------------|
| NL12(1812) | NIN-FB         | CB       | NCB0603R601TR  |
| WL08(1008) | NIN-HC         | SCDS3D18 | NPIS36D        |
| WL05(0805) | NIN-HD         | SCDS4D18 | NPIS42D        |
| WL03(0603) | NIN-HJ         | SCDS4D28 | NPIS43D        |
| WL02(0402) | NIN-HK         | SCDS5D18 | NPIS52D        |
| PD3316     | NPI84          | SCDS5D28 | NPIS53D        |
| PCD0302    | NPI32C         | SCDS6D28 | NPIS63D        |
| PCD0403    | NPI43C         | SCDS6D38 | NPIS64D        |
| PCD0502    | NPI52C         | PSDB1004 | NPIS104F       |
| PCD0504    | NPI54C         | PSDB1005 | NPIS105F       |
| PCD0703    | NPI73C         | PCS73    | NPIS73H        |
| PCD0705    | NPI75C         | PCS74    | NPIS74H        |
| PCD1004    | NPI104C        | PCS124   | NPIS24H        |
| PCD1005    | NPI105C        | PCS125   | NPIS25H        |
| PDH3316    | NPI31P         | PCS127   | NPIS27H        |
| PDH5022    | NPI52P         | SDIA0312 | NPIS32L        |
| PD1608     | NPI16W         | SDIA0412 | NPIS42L        |
| PD3308     | NPI30W         | SDIA0612 | NPIS62L        |
| PD3316     | NPI31W         | SDIA0840 | NPIS80L        |
| PD3340     | NPI34W         | PS1608   | NPIS16R        |
| PD5022     | NPI52W         | PS3316   | NPIS31R        |
| SDB0630    | NPIM74C        | PS5022   | NPIS52R        |
| SDB1040    | NPIM103C       | PCDR0628 | NPIS63T        |
| SCDB2D12   | NPIS21D        | PCDR0730 | NPIS73T        |
| SCDB2D15   | NPIS24D        | PCDR0745 | NPIS75T        |
| SCDB2D18   | NPIS28D        | PCDR1045 | NPIS104T       |



## PANASONIC

| Viking     | PANASONIC  |
|------------|------------|
| NL12(1812) | ELJFB      |
| CL03(0603) | ELJNJ      |
| CL02(0402) | ELJNK      |
| CL02(0402) | ELJQF      |
| CL02(0402) | ELJRF      |
| CL02(0402) | ELJRF(LF)  |
| PSDB1004   | ELLATF     |
| CB         | EXC3BB102H |





## PULSE

| Viking     | PULSE     |
|------------|-----------|
| PD5022     | P0250     |
| PD3316     | P075      |
| PD3308     | P0762     |
| PD1608     | P0770     |
| PCS73      | P1166     |
| PCS74      | P1167     |
| PCS124     | P1168     |
| PCS124     | P1169     |
| PCS125     | P1170     |
| PCS125     | P1171     |
| PCS127     | P1172     |
| PCS127     | P1173     |
| PS1608     | P1174     |
| PDH5022    | P1252     |
| WL02(0402) | PE-0402CD |
| WL03(0603) | PE-0603CD |
| WL05(0805) | PE-0805   |
| WL05(0805) | PE-0805CD |
| WL05(0805) | PE-0805CM |
| WL05(0805) | PE-0805CX |
| WL05(0805) | PE-0805FT |
| WL08(1008) | PE-1008CD |
| WL08(1008) | PE-1008CM |
| WL08(1008) | PE-1008CQ |
| WL08(1008) | PE-1008CQ |
| WL08(1008) | PE-1008CX |
| WL08(1008) | PE-1008FD |
| WL08(1008) | PE-1108CX |
| WL06(1206) | PE-1206CD |



## RENCO

| Viking     | RENCO     |
|------------|-----------|
| PD1608     | RL-1608   |
| NL08(1008) | RL-2505   |
| NL10(1210) | RL-2515   |
| NL12(1812) | RL-2525   |
| PD3308     | RL-3308   |
| PD3316     | RL-3316   |
| PD3340     | RL-3340   |
|            | RL-3901   |
| PD5022     | RL-5022   |
| PCD0403    | RL-6280-1 |
| PCD0504    | RL-6280-2 |
| PCD0703    | RL-6280-3 |
| PCD0705    | RL-6280-4 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## SAMSUNG ELECTRONICS

| Viking     | SAMSUNG ELECTRONICS |
|------------|---------------------|
| CL02(0402) | CIH05T              |
| CL03(0603) | CIH10T              |
| CL05(0805) | CIH21T              |
| ML03(0603) | CIL10               |
| ML05(0805) | CIL21               |
| ML06(1206) | CIL31               |
| CB         | CIM10U121NC         |
| NL12(1812) | CIW32K              |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## SIEMENS

| Viking     | SIEMENS   |
|------------|-----------|
| NL10(1210) | B82422-T  |
| PD5022     | B82479    |
| PS5022     | B82479-G  |
| WL05(0805) | B82498F   |
| CL02(0402) | B82499-A3 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## SMEC

| Viking      | SMEC    |
|-------------|---------|
| CB05 (0805) | FCB0805 |
| CB06 (1206) | FCB1206 |
| ML03(0603)  | MIC0603 |
| NL08(1008)  | WIC1008 |
| NL10(1210)  | WIC1210 |
| NL12(1812)  | WIC1812 |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## SPRAGUE – GOODMAN

| Viking      | SPRAGUE-GOODMAN |
|-------------|-----------------|
| NL12 (1812) | GLB             |
| WL03(0603)  | GLYG            |
| WL02(0402)  | GLZ             |
| WL02(0402)  | GLZG            |



## STETCO

| Viking     | STETCO      |
|------------|-------------|
| WL03(0603) | 0603G       |
| WL05(0805) | 0805G       |
| WL08(1008) | 1008A       |
| WL08(1008) | 1008F(STET) |
| WL08(1008) | 1008G       |
| WL08(1008) | 1008L       |
| WL08(1008) | 1008S       |
| WL08(1008) | 1008T       |



## STETNER

| Viking     | STETNER    |
|------------|------------|
| WL08(1008) | 5501       |
| WL08(1008) | 5501(STD)  |
| WL08(1008) | 5501(STNR) |
| WL06(1206) | 5503       |
| WL06(1206) | 5503(STD)  |
| WL06(1206) | 5503(STNR) |
| WL05(0805) | 5508(CTD)  |
| WL05(0805) | 5508(STNR) |
| CL02(0402) | 5514(STLC) |





## SUMIDA

| Viking   | SUMIDA    | Viking   | SUMIDA     |
|----------|-----------|----------|------------|
| PCD1004  | CD104     | SCDS3D18 | CDRH3D16   |
| PCD1005  | CD105     | SCDS3D18 | CDRH3D16NP |
| PCD0403  | CD43      | SCDS4D18 | CDRH4D18   |
| PCD0403  | CD43NP    | SCDS4D18 | CDRH4D18NP |
| PCD0504  | CD54      | SCDS4D28 | CDRH4D28   |
| PCD0504  | CD54NP    | SCDS4D28 | CDRH4D28NP |
| PCD0703  | CD73      | SCDS5D18 | CDRH5D18   |
| PCD0705  | CD75      | SCDS5D18 | CDRH5D18NP |
| PCD0705  | CD75NP    | PSDB5D28 | CDRH5D28   |
| PCDS105B | CDR105    | PSDB5D28 | CDRH5D28NP |
| PCDS105B | CDR105B   | PCS62B   | CDRH62     |
| PCDS105B | CDR105BNP | PCS64B   | CDRH64     |
| PCDS105B | CDR105NP  | SCDS6D28 | CDRH6D28   |
| PD5022   | CDR156    | SCDS6D28 | CDRH6D28NP |
| PCDS63   | CDR63B    | SCDS6D38 | CDRH6D38   |
| PCDS63   | CDR63BNP  | SCDS6D38 | CDRH6D38NP |
| PCDS74   | CDR74     | PCS73    | CDRH73     |
| PCDS74   | CDR74B    | PCDR0745 | CDRR75     |
| PCDS74   | CDR74BNP  | PCDR1045 | CDRR105    |
| PCDS125B | CDR125    | PCDR1265 | CDRR126    |
| PSDB1004 | CDRH104   | DRGH664  | RCH-664    |
| PSDB1004 | CDRH104R  | DRGH855  | RCH-855    |
| PSDB1005 | CDRH105R  | DRGH875  | RCH-875    |
| PCS124   | CDRH124   | DRGH895  | RCH-895    |
| PCS124   | CDRH124NP | DRGH106  | RCH-106    |
| PCS125   | CDRH125   | DRGR664  | RCR-664D   |
| PCS125   | CDRH125NP | DRGR875  | RCR-875D   |
| PCS127   | CDRH127   | DRGR108  | RCR-108D   |
| SCDB2D11 | CDRH2D11  | DRGR110  | RCR-110D   |
| SCDB2D18 | CDRH2D18  | PD3340   | CDR910     |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## TOKIN

| Viking     | TOKIN        |
|------------|--------------|
| CL03(0603) | N1608LC      |
| CB         | N1608Z121T01 |



## TOKO

| Viking     | TOKO    |
|------------|---------|
| WL02(0402) | LLQ1005 |
| WL03(0603) | LLQ1608 |
| WL05(0805) | LLQ2012 |
| WL08(1008) | 494LYF  |
| CL01(0201) | LL0603  |
| CL02(0402) | LL1005  |
| CL03(0603) | LL1608  |
| PCDR0730   | D73LC   |
| PCDR0730   | D73F/C  |
| PCDR0730   | D73CT   |
| PCDR0745   | D74F/C  |
| PCDR0745   | D75F/C  |
| NL08(1008) | LLM2520 |
| NL10(1210) | LLM3225 |



## TAIYO YUDEN

| Viking     | TAIYO YUDEN |
|------------|-------------|
| CB02       | BK1005      |
| CB03       | BK1608      |
| CB05       | BK2125      |
| CL02(0402) | HK1005      |
| CL03(0603) | HK1608      |
| CL05(0805) | HK2125      |
| NL08(1008) | LEM2520     |
| NL10(1210) | LEM3225     |
| NL12(1812) | LEM4532     |
| ML03(0603) | LK1608      |
| ML05(0805) | LK2125      |
| ML06(1206) | LK3216      |
| SDIA3012   | NR3010      |
| SDIA3012   | NR3012      |
| SDIA4012   | NR4010      |
| SDIA4012   | NR4012      |
| SDIA46012  | NR6012      |



## TDK

| Viking    | TDK             |
|-----------|-----------------|
| CB03      | ACB1608H        |
| CB05Q     | ACB2012H        |
| CB05      | ACB2012M        |
| CB08      | ACB4516M        |
| CB05      | CTCB30-0805     |
| CB05      | HF30ACB201209-T |
| CB06      | HF30ACB321611-T |
| CB12      | HF30ACB322513-T |
| PCDR0628  | SLF6025         |
| PCDR0628  | SLF6028         |
| PCDR0728  | SLF7028         |
| PCDR0730  | SLF7030         |
| PCDR0732  | SLF7032         |
| PCDR0745  | SLF7045         |
| PCDR1045  | SLF7055         |
| PCDR1255  | SLF12555        |
| PCDR1275  | SLF12575        |
| VLH252018 | VLS2520         |
| PDRH0502  | LTF5022         |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## TSC ELECTRONICS

| Viking     | TSC ELECTRONICS |
|------------|-----------------|
| WL03(0603) | ECM             |
| WL03(0603) | FC              |
| WL05(0805) | MCM             |
| WL08(1008) | MCS             |
| PCS125     | PCL             |
| PD3308     | PCS             |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## UNICOM KOREA

| Viking | UNICOM KOREA |
|--------|--------------|
| PCS125 | ST1206       |
| PD3308 | STM12S       |
| PS1608 | STM38        |



## WEST CAP

| Viking    | WEST CAP |
|-----------|----------|
| VLH322520 | 1210PC   |
| VLH575047 | 2220PC   |
| VLH322520 | DINK     |
| VLH575047 | DKM      |
| CB        | MS-90537 |
| CB        | MS-90538 |
| CB        | MS-90539 |
| PD3316    | SSD      |
| PD1608    | SWS      |
| PCD1005   | WCV      |





## WILCO

| Viking   | WILCO    |
|----------|----------|
| CB       | FB1111   |
| CB       | FB1112   |
| CB       | FB1113   |
| CB       | FB1114   |
| CB       | FB1116   |
| PD1608   | FC(WIL)  |
| PCD1005  | LF       |
| PCD0403  | LFB      |
| PCD0504  | RLH      |
| PCD0504  | SFB      |
| PCDS105B | SMBS25   |
| PCDS63B  | SMBS35   |
| PCDS74B  | SMBS45   |
| PD3340   | SMC1210  |
| PD5022   | SMC1812  |
| PSDB1004 | SMCC0603 |
| PCS125   | SMCC0805 |
| PCS127   | SMCC1008 |
| PCS127   | SMS20    |
| SCDS4D18 | SMS30    |
| SCDS4D28 | WMLC0805 |
| SCDS5D28 | WO20     |
| PCS62B   | WO20S    |
| SCDS6D28 | WO30     |
| PCS74    | WO40     |
| PCS74    | WO60     |
| PCS74    | WO60S    |



CBS Europe SRL – Tel.071.7232409 r.a. Fax 071.7232408 – www.cbs.it – cbs@cbs.it

## ULTRACOIL

| Viking     | ULTRACOIL |
|------------|-----------|
| WL03(0603) | 0603CW    |
| WL05(0805) | 0805CW    |
| WL08(1008) | 1008CW    |



## XFMR5 INC

| Viking      | XFMR5 INC   |
|-------------|-------------|
| PD3316      | 1XFS1M      |
| PD1608      | XF26175     |
| PCD1005     | XFSD105     |
| PCD0403     | XFSD43      |
| PCD0504     | XFSD54      |
| PCD0703     | XFSD73      |
| PCDS105B    | XFSDR105SH  |
| PCDS63B     | XFSDR63SH   |
| PCDS74B     | XFSDR74SH   |
| PD3340      | XF5MD2      |
| PD5022      | XF5MD4      |
| PSDB1004    | XFTPRH104   |
| PCS124      | XFTPRH1205  |
| PCS127      | XFTPRH1207  |
| SCDS4D18    | XFTPRH4D18  |
| SCDS4D28    | XFTPRH4D28  |
| SCDS5D18    | XFTPRH5D18  |
| SCDS5D28    | XFTPRH5D28  |
| PCS62B      | XFTPRH62B   |
| SCDS6D28    | XFTPRH6D28  |
| SCDS6D38    | XFTPRH6D38  |
| PCS74       | XFTPRH74    |
| NL08(1008)  | XFWI252018  |
| NL10(1210)  | XFWI322522  |
| NL12(1812)  | XFWI453232  |
| NL12C(1812) | XFWIC453232 |
| WL02(0402)  | XFWICS0402  |
| WL03(0603)  | XFWICS0603  |
| WL05(0805)  | XFWICS0805  |
| WL08(1008)  | XFWICS1008  |
| WL08(1008)  | XFWILS1008  |